

Inlay & Marriage of Metals Workshop with Gustavo Hoefs - Supply List

A soldering set up with silver solder (hard,med,easy) and bench with basic tools such as files, saw frame, 1/0 2/0 blades, pliers, bench pin, and sand paper (220,400,600).

Tools : Riogrande.com / 800-545-6566

- 2x1 inch squares (keep it small) of two or more of the following metals
- 18 ga. copper, brass, nickel, sterling silver or fine silver, sheet
- 18 ga copper, brass, nickel, sterling silver or fine silver, wire
- brass and silver are not easy to solder together - they are not very compatible.
- Handy flux 504084
- #60 or #56 drill bit